



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inpsector
1	200 Alley	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	300 Alley	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	400 Alley	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Ashwood Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Ashwood Ct.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Badeau Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Bank St.	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Beauvior Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Beauvoir Pl.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Beechwood Rd. (Hill Crest to DeForest)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Beechwood Road (DeForest to Union )	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Beekman Ter. (west paved portion)	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Blackburn Rd. (Propect to Valley View)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Crescent Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Crestwood Ln.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Debary Pl.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Druid Hill Dr. (Devon - Mountain)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	rm
1	Druid Hill Dr. (Silver Lake - Devon)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Edgemont Ave. (pvd 2017)	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Elm St.	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Elm St. (Summit to Oak Ridge)	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Essex Rd.	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Fairview Ave.	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Fernwood Rd.	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	rm
1	Harvard St.	0	0	0	0	0	0	0	0	100	0	0	100	10/2/2018	rm
1	Harvey Dr.	0	4	3	0	0	0	0	0	100	0	0	100	9/26/2018	RM
1	Hillside Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Hillview Ter. (Unimproved)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Lenox Rd.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Magnolia Pl.	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Maple St. (Euclid to RR)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Maple St. (RR to Mountain)	0	0	0	0	0	0	0	0	100	0	0	100	9/28/2018	RM
1	Old Springfield Ave.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Plymouth Rd.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Princeton St.	0	0	0	0	0	0	0	0	100	0	0	100	9/26/2018	RM
1	Ridge Rd.	0	0	0	0	0	0	0	0	100	0	0	100	9/26/2018	RM
1	Springfield Ave. (Irving to Broad)	0	0	0	2	0	0	0	0	100	0	0	100	9/28/2018	rm
1	Summit Ave (Morris to Elm)	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Sylvan Rd.	0	0	0	0	0	0	0	0	100	0	0	100	9/24/2018	RM



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inspector
1	Sylvan Ter.	0	0	0	0	0	0	0	0	100	0	0	100	9/24/2018	RM
1	Watchung Pl.	0	0	0	0	0	0	0	0	100	0	0	100	9/26/2018	rm
1	Whittredge Rd.	0	0	0	0	0	0	0	0	100	0	0	100	9/18/2018	RM
1	Woodland Ave. (River to DeForest)	0	0	0	2	2	0	0	0	100	0	0	100	9/26/2018	rm
1	Oak Forest Ln.	0	0	0	0	0	0	0	0	100	0	0	100	10/1/2018	RM
1	Morris Ct.	0	0	0	2	0	0	0	0	100	0	0	100	9/25/2018	RM
1	Cleveland Rd.	0	0	0	0	0	0	0	0	100	0	0	100	10/2/2018	rm
1	Windsor Rd.	0	0	0	0	0	0	0	0	100	0	0	100	10/2/2018	rm
39	Llewellyn Rd.	0	1	0	0	0	0	0	1	99	0	0	99	9/28/2018	RM
40	Colt Rd. (#22 to #57)	0	0	0	0	2	0	0	2	98	0	0	98	9/26/2018	RM
40	Yale St.	0	0	0	2	0	0	0	2	98	0	0	98	9/26/2018	RM
42	Bellevue Ave.	0	1	0	2	0	0	0	3	97	0	0	97	10/2/2018	rm
42	Montview Rd.	0	1	0	2	0	0	0	3	97	0	0	97	9/26/2018	RM
44	Hill Crest Ave.	0	0	0	0	4	0	0	4	96	0	0	96	9/28/2018	RM
44	Shunpike Rd.	0	0	0	2	0	0	0	2	98	0	2	96	9/26/2018	rm
44	Waldron Ave.	0	0	0	4	0	0	0	4	96	0	0	96	9/26/2018	rm
44	Whitesell Ct.	0	1	1	2	0	0	0	4	96	0	0	96	10/2/2018	rm
44	Woodland Ave. (DeForest to Spring.)	0	0	0	2	2	0	0	4	96	0	0	96	9/26/2018	rm
49	Bedford Rd.	0	1	0	2	2	0	0	5	95	0	0	95	9/28/2018	RM
49	Chapel St.	0	1	0	0	4	0	0	5	95	0	0	95	9/28/2018	RM
49	Midland Ter.	0	0	0	0	0	0	5	5	95	0	0	95	9/26/2018	rm
49	Surrey Rd.	0	0	0	0	0	0	5	5	95	0	0	95	9/26/2018	RM
49	Valley View Ave.	0	0	0	0	0	0	5	5	95	0	0	95	9/26/2018	rm
54	Beekman Rd.	0	1	1	2	2	0	0	6	94	0	0	94	9/28/2018	RM
54	Clearview Dr.	0	1	3	2	0	0	0	6	94	0	0	94	10/2/2018	rm
54	Greenfield Ave.	0	1	0	0	0	0	5	6	94	0	0	94	9/18/2018	RM
54	Grove St. (West Side)	0	1	0	0	0	0	5	6	94	0	0	94	10/2/2018	rm
54	Oaklawn Rd.	0	1	0	0	0	0	5	6	94	0	0	94	9/26/2018	RM
59	Dogwood Dr.	0	1	0	4	2	0	0	7	93	0	0	93	10/1/2018	rm
59	Euclid Ave.	0	1	0	4	2	0	0	7	93	0	0	93	10/1/2018	rm
59	Harvey Ct.	0	4	3	0	0	0	0	7	93	0	0	93	9/26/2018	RM
59	Kings Hill Ct.	0	1	1	2	0	0	0	4	96	1	2	93	10/1/2018	rm
59	Miele Pl.	0	1	0	0	0	0	5	6	94	1	0	93	9/26/2018	rm
64	Briant Pkwy.	0	1	3	2	0	0	0	6	94	0	2	92	9/26/2018	RM
64	High St. (Kent to Spring)	0	1	0	0	0	0	5	6	94	0	2	92	9/26/2018	RM
64	Oak Ridge Ave (Montview to Surrey)	0	0	1	2	2	0	0	5	95	1	2	92	9/28/2018	RM
64	Parkview Ter.	0	1	0	2	0	0	5	8	92	0	0	92	9/19/2018	RM
64	Parmley Place	0	1	0	2	0	0	5	8	92	0	0	92	9/19/2018	RM
69	Aubrey St.	0	1	0	4	4	0	0	9	91	0	0	91	9/28/2018	RM



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inpsector
69	DeForest Ave. (Maple to Norwood)	7	0	0	0	2	0	0	9	91	0	0	91	9/26/2018	RM
69	DeForest Ave. (Summit to Maple)	7	0	0	0	2	0	0	9	91	0	0	91	9/26/2018	RM
69	Middle Ave.	0	0	0	4	0	0	5	9	91	0	0	91	9/26/2018	rm
69	Oak Ridge Ave (Surrey to Rotary)	0	0	0	4	2	0	0	6	94	1	2	91	9/25/2018	RM
69	Plain St.	0	0	0	2	2	0	5	9	91	0	0	91	9/24/2018	RM
69	Primrose Pl.	0	4	0	0	0	0	5	9	91	0	0	91	9/26/2018	rm
69	Roosevelt Way	0	0	0	2	0	0	0	2	98	5	2	91	9/28/2018	rm
69	Shadyside Ave.	0	0	0	4	0	0	5	9	91	0	0	91	9/26/2018	RM
78	Ramsey Dr.	0	4	0	2	0	0	0	6	94	2	2	90	10/1/2018	RM
78	Wentworth	7	0	0	0	0	0	0	7	93	1	2	90	10/2/2018	rm
80	Eaton Ct.	0	0	3	2	4	0	0	9	91	0	2	89	9/28/2018	RM
80	Sayre St.	0	1	1	2	0	0	5	9	91	0	2	89	10/2/2018	rm
80	Sunset Dr.	0	0	0	4	2	0	5	11	89	0	0	89	9/26/2018	RM
83	Devon Rd.	0	1	0	0	0	0	10	11	89	1	0	88	9/28/2018	RM
83	Drum Hill Rd.	0	0	3	2	2	0	0	7	93	3	2	88	10/1/2018	rm
83	Passaic Ave. (Const to Spring.)	0	0	0	2	0	0	10	12	88	0	0	88	9/19/2018	RM
87	Prospect Hill Ave.	7	0	0	0	0	0	5	12	88	1	0	87	10/1/2018	rm
87	Woodcroft Rd.	7	0	3	2	0	0	0	12	88	1	0	87	10/2/2018	rm
89	Ashland Rd.	0	1	0	11	2	0	0	14	86	0	0	86	9/28/2018	RM
89	Canoe Brook Pkwy.	7	1	0	4	2	0	0	14	86	0	0	86	10/1/2018	rm
89	Colony Dr.	0	0	0	4	0	0	5	9	91	5	0	86	10/1/2018	rm
89	Glendale Rd.	7	1	1	2	0	0	0	11	89	1	2	86	10/1/2018	RM
89	Kenneth Ct.	0	1	3	0	2	5	0	11	89	1	2	86	10/1/2018	RM
94	Little Wolf Rd.	0	0	3	4	0	0	5	12	88	1	2	85	10/1/2018	RM
94	Oshea Ln	7	1	0	2	0	0	5	15	85	0	0	85	9/26/2018	RM
96	Webster Ave.	7	4	1	2	0	0	0	14	86	0	2	84	10/1/2017	RM
96	Woodmere Dr.	7	1	0	2	0	0	5	15	85	1	0	84	9/26/2018	RM
98	Hawthorne Pl.	7	1	0	0	4	0	5	17	83	0	0	83	9/26/2018	RM
98	John St.	0	1	1	4	4	0	5	15	85	0	2	83	9/26/2018	rm
98	Kent Place Blvd.	0	1	0	0	12	4	0	17	83	0	0	83	9/26/2018	rm
98	Silver Lake Dr.	0	0	17	0	0	0	0	17	83	0	0	83	10/1/2018	RM
98	Springfield Ave. (Kent Place to Irving)	7	1	0	4	0	0	5	17	83	0	0	83	9/26/2018	RM
103	Doremus St.	0	1	1	2	2	0	10	16	84	0	2	82	10/2/2018	rm
103	Lowell Ave.	7	4	1	2	0	0	0	14	86	2	2	82	10/1/2018	RM
103	Railroad Ave. (At Village Green)	7	1	1	2	0	0	5	16	84	0	2	82	9/26/2018	RM
103	Woodfern Rd.	7	1	3	4	2	0	0	17	83	1	0	82	10/3/2018	RM
107	Brantwood Dr.	7	0	1	4	4	0	0	16	84	3	0	81	10/3/2018	RM
107	Stockton Rd.	0	4	0	4	0	5	5	18	82	1	0	81	9/28/2018	RM
107	Valemont Way	7	1	0	11	0	0	0	19	81	0	0	81	10/1/2018	rm



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inspector
	110 Blackburn Rd. (Springfield to Prospect)	7	1	0	0	2	0	10	20	80	0	0	80	10/1/2018	rm
	110 Canterbury Ln.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Club Dr.	7	1	1	4	2	0	0	15	85	0	5	80	10/1/2018	RM
	110 Cottage Ln.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	rm
	110 Dale Dr.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Dennis Pl.	7	0	1	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Edgewood Dr.	7	1	1	2	2	0	0	13	87	5	2	80	9/26/2018	RM
	110 Freemont Rd.	7	1	0	2	0	5	5	20	80	0	0	80	9/25/2018	RM
	110 Gloucester Rd.	7	1	0	0	2	5	5	20	80	0	0	80	9/26/2018	RM
	110 Joanna Way	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	rm
	110 Milton Ave.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Norwood Ave.	7	0	1	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Rotary Dr.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Rotary Ln.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 School Ave.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Sheridan Rd.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 Twombly Dr.	7	1	1	2	2	0	5	18	82	2	0	80	10/1/2018	rm
	110 Warwick Rd.	7	4	3	2	0	0	0	16	84	2	2	80	10/2/2018	rm
	110 Weaver St.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	110 West Ln.	7	1	0	2	0	5	5	20	80	0	0	80	9/26/2018	RM
	130 Colt Rd. (#57 to Ashland Rd)	0	4	3	4	2	5	0	18	82	3	0	79	10/1/2018	rm
	130 Hickory Rd.	0	4	3	4	2	0	5	18	82	1	2	79	9/26/2018	RM
	130 New England Ave. (Spring. to Locust)	7	1	3	0	0	0	5	16	84	5	0	79	9/26/2018	RM
	130 Stacie Ct.	15	4	0	0	0	0	0	19	81	2	0	79	10/1/2018	RM
	130 Van Dyke Pl.	0	10	0	11	0	0	0	21	79	0	0	79	9/26/2018	rm
	135 Blair Pl.	7	4	1	0	0	0	5	17	83	0	5	78	10/2/2018	rm
	135 Division Ave.	7	1	3	2	2	0	5	20	80	0	2	78	10/1/2018	rm
	135 Glen Oaks Ave.	15	1	1	0	0	0	5	22	78	0	0	78	10/1/2018	RM
	135 Highland Dr.	7	1	1	4	2	5	0	20	80	0	2	78	10/1/2018	RM
	135 Lewis Ave.	0	1	1	2	12	0	5	21	79	1	0	78	9/18/2018	RM
	140 Beverly Rd.	0	1	17	0	0	0	0	18	82	3	2	77	9/26/2018	RM
	140 Cedric Rd.	7	4	3	0	2	0	0	16	84	5	2	77	10/2/2018	rm
	140 Dorset Ln.	7	4	1	4	2	0	5	23	77	0	0	77	10/2/2018	rm
	140 George St.	7	1	1	11	0	0	0	20	80	1	2	77	9/26/2018	RM
	140 Harrison Ct.	15	1	0	2	0	0	0	18	82	0	5	77	10/2/2018	rm
	140 Lafayette Ave.	7	4	0	0	0	5	5	21	79	0	2	77	10/1/2018	RM
	140 Londonderry	7	4	1	4	2	0	0	18	82	5	0	77	9/28/2018	RM
	140 Union Pl.	7	1	1	4	0	5	5	23	77	0	0	77	9/26/2018	RM
	148 Knob Hill Dr.	7	0	3	2	12	0	0	24	76	0	0	76	10/1/2018	rm



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inspector
148	Lincoln Ave.	7	4	3	4	4	0	0	22	78	2	0	76	10/1/2018	RM
148	North St.	7	10	1	4	2	0	0	24	76	0	0	76	9/26/2018	rm
148	Sheffield Rd.	7	4	1	2	0	0	5	19	81	3	2	76	10/2/2018	rm
152	Arden Pl.	7	4	1	2	2	5	0	21	79	1	3	75	10/3/2018	RM
152	Carleen Ct.	7	4	3	4	4	0	0	22	78	1	2	75	10/1/2018	RM
152	Greenbriar Dr.	0	1	1	11	12	0	0	25	75	0	0	75	10/1/2018	rm
152	Iris Rd.	7	4	0	0	4	0	5	20	80	0	5	75	10/2/2018	rm
152	Linda Ln.	7	10	3	0	0	0	5	25	75	0	0	75	10/1/2018	RM
152	Montrose Ave.	7	4	0	2	12	0	0	25	75	0	0	75	10/1/2018	RM
158	Argyle Ct.	15	4	0	2	0	0	0	21	79	2	3	74	9/28/2018	RM
158	Dunnder Dr.	7	1	0	4	4	5	5	26	74	0	0	74	10/1/2018	rm
158	Gates Ave.	7	4	0	0	12	0	0	23	77	1	2	74	10/1/2018	RM
158	Glenwood Pl.	7	4	1	4	0	0	10	26	74	0	0	74	10/1/2018	rm
162	Colt Rd. (Blackburn to #22)	0	1	3	4	4	0	5	17	83	5	5	73	10/1/2018	rm
162	Cromwell Pkwy.	7	4	1	0	0	10	5	27	73	0	0	73	10/2/2018	rm
162	Hughes Pl.	0	1	1	11	12	0	0	25	75	0	2	73	9/25/2018	RM
162	Ruthven Pl.	7	4	1	4	2	5	0	23	77	1	3	73	10/2/2018	rm
162	Stiles Rd.	0	10	3	11	2	0	0	26	74	1	0	73	10/1/2018	rm
162	Walnut St.	7	1	1	11	4	0	0	24	76	1	2	73	10/2/2018	rm
168	Colonial Rd.	7	1	3	2	2	0	5	20	80	5	3	72	10/1/2018	RM
168	Evergreen Rd.	15	1	3	2	4	0	0	25	75	1	2	72	10/1/2018	rm
168	McGregor Rd.	7	1	3	4	0	0	5	20	80	3	5	72	10/2/2018	rm
168	Nassau Dr.	15	1	0	0	12	0	0	28	72	0	0	72	10/2/2018	rm
172	Blackburn Rd. (Valley View to Division)	7	0	0	0	12	0	10	29	71	0	0	71	10/1/2018	rm
172	Edgewood Rd.	15	4	1	2	2	0	0	24	76	0	5	71	9/26/2018	RM
172	Hobart Ave (Spring. To Rt. 24)	15	1	0	2	4	0	5	27	73	0	2	71	9/18/2018	RM
172	Malvern Dr.	7	4	3	4	0	5	5	28	72	1	0	71	9/28/2018	rm
172	New England Ave. (Kent to Spring.)	7	4	0	11	2	0	5	29	71	0	0	71	9/26/2018	RM
172	Willow Rd. (Residential Side)	7	1	1	4	4	0	10	27	73	0	2	71	9/26/2018	RM
178	Oakley Ave.	7	4	0	4	0	5	10	30	70	0	0	70	10/1/2018	RM
178	Pine Ridge Dr.	7	4	3	4	2	0	5	25	75	0	5	70	10/1/2018	RM
178	William St.	0	0	0	11	12	5	0	28	72	0	2	70	10/2/2018	rm
181	Dayton Rd.	7	10	3	4	0	0	5	29	71	2	0	69	9/26/2018	RM
181	Pembroke Rd.	7	1	3	2	2	5	5	25	75	3	3	69	10/1/2018	RM
181	Tulip St. (Ashland to Springfield)	7	1	3	2	2	0	10	25	75	1	5	69	10/2/2018	rm
181	Wade Dr.	0	4	1	4	4	5	5	23	77	3	5	69	9/26/2018	rm
185	Myrtle Ave.	0	10	0	2	12	0	5	29	71	0	3	68	10/2/2018	rm
186	Glenn Ave.	7	4	1	2	12	0	5	31	69	2	0	67	9/28/2018	RM
186	Madison Ave.	7	4	3	4	4	5	5	32	68	1	0	67	10/1/2018	RM



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inspector
186	Mount Vernon	17	1	3	2	0	5	5	33	67	0	0	67	9/26/2018	rm
186	Ox Bow Ln.	0	0	17	0	12	0	0	29	71	2	2	67	10/1/2018	RM
186	Robinhood Rd.	7	4	3	4	0	0	10	28	72	3	2	67	10/2/2018	rm
186	Russell Pl.	15	1	1	2	4	5	5	33	67	0	0	67	9/26/2018	RM
192	Cedar St.	15	4	3	4	0	0	5	31	69	1	2	66	9/26/2018	RM
192	Garden Rd.	15	4	3	0	0	5	5	32	68	0	2	66	10/1/2018	rm
192	Orchard St. (End to Morris Avenue)	7	10	1	4	2	0	5	29	71	3	2	66	9/26/2018	RM
195	Templar Way	7	4	0	4	12	0	5	32	68	1	2	65	9/26/2018	RM
196	Stony Hill Ct.	0	0	36	0	0	0	0	36	64	0	0	64	10/1/2018	RM
196	Washington Ave.	7	1	1	2	12	0	10	33	67	1	2	64	9/26/2018	rm
198	Baltusrol Pl.	0	1	1	11	12	5	0	30	70	2	5	63	9/26/2018	RM
198	High St. (Spring. to Prospect)	7	4	3	2	4	10	5	35	65	1	1	63	9/26/2018	RM
198	Sherman Ave.	7	4	1	4	0	0	21	37	63	0	0	63	9/26/2018	RM
201	Canoe Brook Pl.	0	1	17	4	2	5	5	34	66	2	2	62	10/1/2018	rm
201	Irving Pl.	7	4	3	11	12	0	0	37	63	1	0	62	10/2/2018	rm
201	Portland Rd.	7	4	1	4	2	10	10	38	62	0	0	62	10/2/2018	rm
204	Prospect St.	7	1	3	4	4	5	10	34	66	3	2	61	9/28/2018	RM
204	South St.	7	10	3	4	12	0	0	36	64	1	2	61	9/26/2018	rm
204	Wild Wood Ln.	7	4	1	2	12	0	10	36	64	1	2	61	10/2/2018	rm
207	Colony Ct.	7	10	3	11	4	0	5	40	60	0	0	60	10/1/2018	rm
208	Hartley Rd.	7	1	17	0	12	0	0	37	63	2	2	59	9/26/2018	RM
208	Lorraine PL.	15	1	0	3	4	5	10	38	62	3	0	59	9/26/2018	rm
208	Lorraine RD.	15	1	0	3	4	5	10	38	62	3	0	59	9/26/2018	rm
211	Karen Way	7	4	3	4	2	5	10	35	65	5	2	58	10/2/2018	rm
211	Sweet Briar Rd.	15	10	3	4	4	0	5	41	59	1	0	58	9/26/2018	RM
213	Friartuck Cir.	15	4	0	4	2	5	5	35	65	3	5	57	10/1/2018	rm
214	Faitoute Ct.	15	10	3	4	0	10	0	42	58	0	2	56	9/26/2018	RM
215	Blackburn Pl.	15	4	3	4	4	10	5	45	55	0	0	55	10/1/2018	rm
215	Mead Ct.	7	10	17	4	0	5	0	43	57	0	2	55	9/26/2018	rm
215	Rose Ln.	15	1	1	4	4	5	10	40	60	0	5	55	9/28/2018	rm
218	Pearl St.	15	4	1	4	2	5	10	41	59	3	2	54	9/26/2018	RM
218	Rowan Rd.	15	4	3	4	2	5	5	38	62	5	3	54	10/2/2018	rm
220	West End Ave. (Dunnder to Passaic)	15	4	3	4	2	10	5	43	57	3	2	52	10/1/2018	RM
221	Fay Pl.	7	4	3	4	4	10	10	42	58	5	2	51	10/1/2018	rm
221	Gary Rd.	15	10	3	11	0	10	0	49	51	0	0	51	9/26/2018	RM
223	Beekman Ter. (east paved portion)	15	4	3	4	4	10	5	45	55	3	2	50	10/1/2018	rm
224	Ascot Way	7	10	3	4	0	5	21	50	50	1	0	49	9/28/2018	RM
224	Brook Ct.	15	10	3	4	4	5	10	51	49	0	0	49	xxx	xxx
226	Brainerd Rd.	15	4	3	4	4	10	5	45	55	5	2	48	10/2/2018	rm



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	7- Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inpsector
227	Denman Pl.	15	4	1	4	23	5	0	52	48	0	2	46	9/28/2018	Rm
227	Oak Ridge Ave (Mountain to Montview)	27	4	1	2	12	0	5	51	49	1	2	46	9/26/2018	RM
229	West End Ave. (Passaic to New Prov)	15	4	17	2	2	5	5	50	50	3	2	45	10/1/2018	RM
230	Maple St. (Euclid toDeforest)	15	4	1	11	12	5	10	58	42	0	0	42	9/28/2018	RM
231	Edison Dr.	15	10	17	4	0	0	10	56	44	3	0	41	9/26/2018	RM
231	Laurel Ave. (North Block)	15	4	17	4	4	0	10	54	46	5	0	41	9/25/2018	RM
231	Springfield Ave. (Morris to Kent Place)	15	4	3	4	2	10	21	59	41	0	0	41	9/18/2018	RM
234	Elm Pl.	27	1	1	4	12	5	10	60	40	0	0	40	9/26/2018	RM
234	Linden Pl.	7	4	3	4	12	10	10	50	50	5	5	40	9/25/2018	RM
236	Franklin Pl.	15	4	3	4	23	5	5	59	41	0	2	39	9/26/2018	RM
236	Michigan Ave.	15	1	3	4	23	5	0	51	49	5	5	39	9/26/2018	RM
236	Oak Knoll Rd.	15	4	3	2	12	5	10	51	49	5	5	39	9/26/2018	RM
239	New Providence Ave.	7	4	3	11	12	10	5	52	48	5	5	38	9/25/2018	RM
239	Tulip St. (Mountain to Ashland)	7	1	3	2	12	10	21	56	44	1	5	38	10/2/2018	rm
239	Westminster Rd.	15	4	3	4	23	10	0	59	41	1	2	38	9/18/2018	RM
242	Winchester Rd.	7	4	3	2	12	10	21	59	41	2	2	37	9/25/2018	RM
243	Larned Rd. (Mountain to Myrtle)	15	4	3	4	4	10	21	61	39	3	0	36	9/25/2018	RM
243	Manor Hill Rd.	15	10	3	4	12	10	10	64	36	0	0	36	10/1/2018	RM
245	Crest Acre Ct.	15	4	3	11	4	10	10	57	43	5	3	35	9/25/2018	RM
246	Hobart Ave (Franklin to Springfield)	7	0	17	4	2	21	5	56	44	5	5	34	9/25/2018	RM
246	Tanglewood Dr.	27	10	3	4	2	5	10	61	39	2	3	34	9/24/2018	RM
248	Hobart Rd.	27	0	17	2	2	5	10	63	37	4	0	33	9/26/2018	RM
248	Oakland Pl.	15	4	17	4	2	10	10	62	38	3	2	33	9/18/2018	RM
250	Edgar St.	15	10	3	4	2	10	21	65	35	3	0	32	9/26/2018	RM
251	Caldwell Ave.	7	10	3	4	12	10	21	67	33	0	2	31	9/26/2018	RM
251	West End Ave. (Dunnder to Dead End)	15	4	17	4	2	10	10	62	38	5	2	31	9/25/2018	RM
253	Pine Grove Ave.	15	10	3	11	4	10	21	74	26	0	0	26	9/24/2018	RM
254	Wallace Rd.	15	1	3	11	4	10	21	65	35	5	5	25	9/24/2018	RM
255	Park Ave.	15	10	17	11	12	5	0	70	30	5	2	23	9/26/2018	RM
256	Huntley Rd.	15	4	3	11	12	10	21	76	24	0	2	22	9/25/2018	RM
256	Ridgedale Ave.	15	4	17	4	2	21	5	68	32	5	5	22	9/26/2018	RM
258	Butler Pkwy.	7	10	36	11	4	0	5	73	27	5	2	20	9/25/2018	RM
259	Beacon Rd.	15	0	36	0	12	5	5	73	27	5	3	19	9/26/2018	RM
260	Clark St.	15	4	17	4	12	5	21	78	22	2	2	18	9/26/2018	RM
260	Locust Dr. (Springfield to Tulip)	7	1	36	2	4	21	5	76	24	3	3	18	9/24/2018	RM
262	Meadowbrook Ct.	15	4	17	11	4	10	21	82	18	3	2	13	9/24/2018	RM
263	Risk Ave.	15	4	17	4	4	21	21	86	14	1	2	11	10/1/2018	RM
264	Industrial Pl.	15	4	17	11	4	10	21	82	18	5	3	10	9/25/2018	RM
265	Dorchester Rd.	7	4	17	4	23	10	21	86	14	3	2	9	9/24/2018	RM



**City of Summit  
Engineering Division  
Citywide Road Assessment  
Completed October 2018**

Rank	Street	Alligator Cracking 15-27-38	Block Cracking 1-1-4-10	Distortions 1-3-17-36	Longitudinal & Transversal Cracking 2-4-11-22	Patching & Utility Cut Patching 2-4-12-23	Rutting & Depression 5-10-21-30	Weathering & Raveling 5-10-21-30	Total Cracking Deduction	Score	Curb 0-2-3-5	Drainage 0-2-3-5	Total Points	Date	Inpsector
	266 Henry St.	15	10	3	22	2	21	21	94	6	5	0	1	9/26/2018	RM
	267 Railroad Ave. (At Post Office)	27	4	1	17	12	21	21	103	-3	0	0	-3	9/24/2018	RM
	268 Laurel Ave. (South Block)	15	4	17	11	12	21	21	101	-1	5	0	-6	9/24/2018	RM
	269 Park Pl.	27	10	17	22	2	10	21	109	-9	0	0	-9	9/18/2018	RM
	270 Willow Rd. (Industrial Side)	27	10	17	22	4	5	21	106	-6	5	5	-16	10/2/2018	rm
	271 Beekman Ter. (unpaved portion)	38	10	36	22	23	30	30	189	-89	3	2	-94	10/1/2018	rm
	271 Grove St. (Unimproved)	38	10	36	22	23	30	30	189	-89	5	0	-94	9/26/2018	rm
	273 Larned Rd. - (Unimproved)	38	10	36	22	23	30	30	189	-89	5	5	-99	9/18/2018	RM
	273 Old Coach Rd. (Unimproved)	38	10	36	22	23	30	30	189	-89	5	5	-99	9/18/2018	RM
	273 Stanley Ave (Unimproved)	38	10	36	22	23	30	30	189	-89	5	5	-99	10/1/2018	RM

**NON - CITY ROADS**

- Baltusrol Rd.(COUNTY)
- Beech Spring Drive (Private)
- Broad St. (COUNTY)
- Chatham Rd. (COUNTY)
- Chestnut Ave. (CITY HALL PARKING LOT)
- Constantine Pl. (COUNTY)
- Glenside Ave. (COUNTY)
- Interstate 78 (STATE)
- Lower Overlook Rd. (PRIVATE)
- Morris & Essex Tpk. Route 124 (STATE)
- Morris Ave. (COUNTY)
- Mountain Ave.(COUNTY)
- Orchard St. - Broad to Briant (COUNTY)
- Passaic Ave. (COUNTY)
- River Rd. (COUNTY)
- Route 24 (STATE)
- Springfield Ave. (West of Morris) (COUNTY)
- Upper Overlook Rd. (PRIVATE)